Energy performance certificate (EPC)

94a, Church Road CROYDON CR0 1SD	Energy rating	Valid until: Certificate number:	8 February 2029 8761-7722-6220-7288-2902
Property type Top-floor flat			

Total floor area

49 square metres

Rules on letting this property

Properties can be let if they have an energy rating from A to E.

You can read guidance for landlords on the regulations and exemptions (https://www.gov.uk/guidance/domestic-private-rented-property-minimum-energy-efficiency-standard-landlord-guidance).

Energy efficiency rating for this property

This property's current energy rating is D. It has the potential to be C.

See how to improve this property's energy performance.

Score	Energy rating	Current	Potential
92+	Α		
81-91	B		
69-80	С		78 C
55-68	D	68 D	
39-54	E		
21-38	F		
1-20	G		

The graph shows this property's current and potential energy efficiency.

Properties are given a rating from A (most efficient) to G (least efficient).

Properties are also given a score. The higher the number the lower your fuel bills are likely to be.

For properties in England and Wales:

- the average energy rating is D
- the average energy score is 60

Breakdown of property's energy performance

This section shows the energy performance for features of this property. The assessment does not consider the condition of a feature and how well it is working.

Each feature is assessed as one of the following:

- very good (most efficient)
- good
- average
- poor
- very poor (least efficient)

When the description says "assumed", it means that the feature could not be inspected and an assumption has been made based on the property's age and type.

Feature	Description	Rating
Wall	Solid brick, as built, no insulation (assumed)	Very poor
Roof	Pitched, 150 mm loft insulation	Good
Window	Fully double glazed	Average

Feature	Description	Rating
Main heating	Boiler and radiators, mains gas	Good
Main heating control	Programmer, TRVs and bypass	Average
Hot water	From main system	Good
Lighting	Low energy lighting in 67% of fixed outlets	Good
Floor	(another dwelling below)	N/A
Secondary heating	None	N/A

Primary energy use

The primary energy use for this property per year is 235 kilowatt hours per square metre (kWh/m2).

What is primary energy use?

Environmental impact of this property

This property's current environmental impact rating is D. It has the potential to be B.

Properties are rated in a scale from A to G based on how much carbon dioxide (CO2) they produce.

Properties with an A rating produce less CO2 than G rated properties.

An average household produces

6 tonnes of CO2

This property produces

This property's potential production

1.2 tonnes of CO2

2.0 tonnes of CO2

By making the <u>recommended changes</u>, you could reduce this property's CO2 emissions by 0.8 tonnes per year. This will help to protect the environment.

Environmental impact ratings are based on assumptions about average occupancy and energy use. They may not reflect how energy is consumed by the people living at the property.

Improve this property's energy performance

By following our step by step recommendations you could reduce this property's energy use and potentially save money.

Carrying out these changes in order will improve the property's energy rating and score from D (68) to C (78).

Do I need to follow these steps in order?

Step 1: Internal or external wall insulation

Typical installation cost



£4,	,000	-	£1	4,	000	
£4,	,000	-	£1	4,	000	

Typical yearly saving		
	£102	
Potential rating after completing step 1		
	75 C	
Step 2: Low energy lighting		
Typical installation cost		
	£15	
Typical yearly saving		
	£11	
Potential rating after completing steps 1 and 2		
	75 C	

Step 3: Replace boiler with new condensing boiler

Typical installation cost £2,200 - £3,000 Typical yearly saving

£39

Paying for energy improvements

You might be able to get a grant from the <u>Boiler Upgrade Scheme (https://www.gov.uk/apply-boiler-upgrade-scheme)</u>. This will help you buy a more efficient, low carbon heating system for this property.

Estimated energy use and potential savings

Based on average energy costs when this EPC was created:

Estimated yearly energy cost for this property

Potential saving if you complete every step in order

It is not based on how energy is used by the people living at the property.

Heating use in this pr	operty	
Heating a property usually makes up the m	ajority of energy costs.	
Estimated energy used to h	eat this property	
Type of heating	Estimated energy used	
Space heating	4429 kWh per year	
Water heating	1684 kWh per year	
Potential energy savings by	installing insulation	
Type of insulation	Amount of energy saved	
Loft insulation	287 kWh per year	
Solid wall insulation	2003 kWh per year	

The estimated cost shows how much the average household would spend in this property for heating, lighting and hot water.

Saving energy in this property

Find ways to save energy in your home.

Contacting the assessor and accreditation scheme

This EPC was created by a qualified energy assessor.

If you are unhappy about your property's energy assessment or certificate, you can complain to the assessor directly.

If you are still unhappy after contacting the assessor, you should contact the assessor's accreditation scheme.

78 | C

£151

Accreditation schemes are appointed by the government to ensure that assessors are qualified to carry out EPC assessments.

Assessor contact details

Assessor's name

Christopher Kulski

Telephone

02033978220

Email

support@epconline.co.uk

Accreditation scheme contact details

Accreditation scheme Stroma Certification Ltd

Assessor ID

STRO032567

Telephone

0330 124 9660

Email

certification@stroma.com

Assessment details

Assessor's declaration No related party

Date of assessment 8 February 2019

Date of certificate

9 February 2019

Type of assessment



Other certificates for this property

If you are aware of previous certificates for this property and they are not listed here, please contact us at <u>dluhc.digital-services@levellingup.gov.uk</u> or call our helpdesk on 020 3829 0748 (Monday to Friday, 9am to 5pm).

There are no related certificates for this property.