

## Complete Energy Certificates Ltd Complete Energy Certificates Ltd

Company / Inst	aller			ob Addres	5			Client / Lar	dLord		
Engineer				Name Carol Meldrum				Name			
Company				Address	94a			Company	247 Home Rescue	e	
Address					Church Road			Address	Unit 3 Petre Crt		
Chapel View				South Norwood				Clayton Le Moors			
South Croydon								Lancashire			
	Surrey			Post Code				Post Code Tel. No			
Post Code	-			Tel. No					BB5 5HY		
Tel No. 020 8651 0170									01254 355581		
Gas Safe Reg No. 153412											
ID Card No.											
Appliance Deta	ails										
Туре	Boiler		Hig	High Combustion Performance Readings			Low Comb	ustion Performance	e Readings		
Make	Ideal			CO/Co2 Ratio	0.0008			CO/Co2 Ratio	0.0006		
Model	Aodel LogicCombiC24				CO (ppm) CO2 %	66			CO (ppm)	47	
Location (Position/Room) Kitchen Cupboard					8.5			CO2 %	7.7		
Serial No. AFQ 21398000905581		1 2022									
Safety Checks											
Appliance is operating correctly Ye			Yes			Appliance flueing is safe			Yes		
Appliance conforms to current safety standards			Yes			Appliance ventilation is safe			Yes		
Appliance/system controls checked/adjusted			Yes			Emission/combustion test			Pass		
Operating pressure (mbar) 21			21			Burner pressure/Gas rate correct			Yes		
Heat Input (kW)		24			Tightness Test carried out			Yes			
Central heating	g Annual Service ar	nd Plumbing Inspec	tion								
Boiler/warm air working correctly Yes			Yes	Warm air/outlet grills working correctly				No			
Hot water cylinder condition checked and in working order No			No			Visible pipework free from water leaks			Yes		
Programmer/timer and all controls working correctly Yes			Yes			Magnetic System filter fitted (where applicable)		Yes			
				Water quality/level of inhibitor accept			hibitor accepta	ble	Yes		
Appliance / sys <sup>-</sup>	tem advice and re	commendations									
Approved audible Carbon Monoxide Alarm fitted* Yes			Yes			Safety warning/advice notice explained and left			No		
Appliance is safe Yes			Yes			Recommended appliance replacement - see advice			No		
All functional parts available Yes			Yes			System improvement(s) recommended - see advice			No		
*Δlthough regular	servicing is essential	an audible Carbon Mor	noxide Alarm is an early	warning dev	vice that keeps working 2	4 hours a day should an unfor	eseen event oc	cur Battery or	erated models have	e a 4-5 vear lifespan. It is reco	ommended that

customers check the expiry date periodically.

NEXT GAS SERVICE IS DUE ON OR BEFORE	31-May-2023
--------------------------------------	-------------

Engineer Comments Signatures   Condense cleaned Issued by: Signed Received by: Signed Date 31-May-2022				
Condense cleaned Issued by: Signed Received by: Signed Date 31-May-2022	Engineer Comments	Signatures		
	Condense cleaned	Issued by: Signed	Received by: Signed	Date 31-May-2022
Pressure topped up	Pressure topped up			
Boiler working well	Boiler working well			
Print Name: Jamie Hoddinott Print Name:		Print Name: Jamie Hoddinott	Print Name:	